



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 22, 2008

Reviewed ABZ

Mine Name: Dugway Pass	Permit Number: S0230091
Operator Name: Davies, Wingle & Davies, Inc.	Inspection Date: May 14, 2008
Inspector(s): L Heppler	Time: 5:00 pm
Other Participants: None	Mine Status: Act

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: None listed **Bond Amount:** \$18,750

Purpose of Inspection: This was a routine annual inspection

Inspection Summary: No additional ground disturbance was noted on the site since he last inspection (10-24-07). The site was visited and the disturbance was limited to a road and trench at the end of the road. The actual trench area needs some site clean up as junk (lights, pipe, litter) was scattered about. There is now a small winkie type drill rig located in the trench and a grizzly screen located on site. There was a pop-up camper and drilling mud located further down the road.

Photos were taken to document site conditions.

Conclusions and Recommendations: Continue to monitor this site when in the area. The operator needs to maintain a clean site when not mining as well as saving topsoil from areas disturbed to replace when mining is done.

Inspector's Signature

LAH:pb

cc: Roger Davies

Will Stokes - SITLA

Attach - GIS

O:\M023-Juab\S0230091-Dugwaypass\inspections\Insp_DugwayPass_05-14-08.doc

Resubmit

06-30-11

Photos Taken 05-14-08

